

PHASE 3 of 6

SCHEDULE




Phase 3 of 6

Work Schedule:
Mid-April to Late-June (2019)

Operational Runway:
Runway 18R/36L (4,146 Feet)
Runway 18L/36R

Closed Runway:
Runway 6/24

LEGEND

-  Operational Surface Area
-  Closed Surface Area
-  Work Area

Phase 3 (70 Calendar Days)

